



CODE ENFORCEMENT BOARD HEARING AGENDA

SEPTEMBER 24, 2019 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

PLEASE NOTE THAT TWO-WAY COMMUNICATION BETWEEN MEMBERS OF THE BOARD IS PROHIBITED BY SUNSHINE LAW. PLEASE DO NOT REPLY TO ANY BOARD MEMBER. ALL DISCUSSIONS ON RELEATIVE TO THE AGENDA SHOULD TAKE PLACE AT SCHEDULED BOARD MEETINGS.

Two or more City Commissioners and/or Advisory Board members may be present at this meeting. If a person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing, he/she will need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

If you desire auxiliary services to assist in viewing or hearing the meetings or reading agendas and minutes for the meetings, please contact the City Clerk's office at (954) 828-5002 and arrangements will be made to provide these services for you.

Unless otherwise stated, these items are quasi-judicial. Board members shall disclose any communication or site visits they have had pursuant to Section 47-1.13 of the ULDR. All persons speaking on a quasi-judicial matter will be sworn in and will be subject to cross-examination.

Board Members: Patrick McGee, Chair • Mark Booth, Vice Chair • Julie Lurie

- Peter Cooper Chris Evert William Marx Justin Beachum Terry Nolen (alternate)
- Michael Madfis (alternate) Lahki Mohnani (alternate) Board Attorney: Bruce Jolly

HEARING SCHEDULED

CASE NO: CE19041215 CASE ADDR: 1430 SW 10 ST

OWNER: MCLAREN, KRISTEN MARIE H/E

OJITO, DANIEL

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2017) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. NEW WOODEN FENCE INSTALLED ON PROPERTY.

CASE NO: CE18011809
CASE ADDR: 5950 NE 14 RD

OWNER: CAVANAUGH, KEVIN P

KEVIN P CAVANAUGH LIV TR

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS OF THE POOL DECK WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE19061325 CASE ADDR: 1900 S OCEAN DR

OWNER: BREAKWATER TOWERS CORP

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. MAIN SHUT OFF VALVES REPLACED.
2. REPLACED PUMP STATION SYSTEM.

CASE NO: CE18091741 CASE ADDR: 500 SW 12 ST

OWNER: PP CAPITAL PARTNERS LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

EXTERIOR WINDOWS AND DOORS.
 INTERIOR FRAMING AND DRYWALL.

3. WIRE AND STUCCO OF FRONT WOOD FRAME BUILDING.

4. CORRUGATED OVERHANG AT FRONT ENTRANCE.

5. BATHROOM AND KITCHEN RENOVATION.

6. NEW ELECTRICAL OUTLETS AND SWITCHES.

7. NEW ELECTRICAL PANEL.

8. HIGH-HAT LIGHTS ON CEILING.

9. MECHANICAL A/C UNIT AND EXHAUST FANS.

CASE NO: CE19022026
CASE ADDR: 1121 SW 19 ST
OWNER: KARSKO, DANIEL
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

NEW INTERIOR WALL.
 A/C UNIT CHANGEOUT.

3. ELECTRICAL PANEL REPLACED.

CASE NO: CE19041534
CASE ADDR: 1109 NE 16 TER
OWNER: CRICKETT, JOHN J
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ILLEGAL CONVERSION OF A FOUR UNIT EFFICIENCY INTO A FIVE UNIT WITHOUT A PERMIT.

2. METER ROOM AND UTILITY ROOM MISSING DRYWALL ON FIRE SEPARATION WALL.

- 3. STRUCTURE ROOF BUILT OVER WASHING MACHINE AREA.
- 4. PLUMBING, ELECTRICAL AND DRAINAGE LINE FOR WASHING MACHINE.
- 5. REPLACED FRONT PORCH ROOF SUPPORT WITH 4X4 COLUMN SUPPORTS.

FBC(2017) 111.1.1

THE USE AND THE OCCUPANCY OF THIS PARCEL AND BUILDING HAVE BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A FOUR UNIT EFFICIENCY WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE18110489
CASE ADDR: 1830 NW 26 TER

OWNER: BLD CONSTRUCTION INC

SAINT JEAN, YVANE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR AND EXTERIOR ALTERATIONS WITHOUT THE

REQUIRED PERMITS AND/OR INSPECTIONS.

.-----

CASE NO: CE18110574
CASE ADDR: 901 SE 14 ST
OWNER: DERLLY, KAREN
INSPECTOR: BOBBY MASULA

VIOLATIONS: 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. NEW KITCHEN INSTALLED WITH PLUMBING, ELECTRIC,

DRYWALL.

2. NEW WINDOWS INSTALLED.

3. NEW MINI SPLIT.

CASE NO: CE19051349 CASE ADDR: 1309 NE 1 AV

OWNER: WINNER, GARRETT E

HERRERA, GUILLERMINA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

1. A LARGE WOOD DECK/STRUCTURE BEING BUILT WITHOUT

THE REQUIRED PERMITS AND/OR INSPECTIONS.

.-----

CASE NO: CE19061832 CASE ADDR: 1609 SE 2 CT

OWNER: LESLEE WILLIAMS WALKER REV TR

WALKER, LESLEE WILLIAMS TRSTEE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

1. INTERIOR RENOVATIONS INCLUDING ELECTRICAL AND

PLUMBING PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE16071180
CASE ADDR: 512 NW 15 TER
OWNER: SABRA 52 LLC
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. THE INTERIOR FLOOR PLAN CONFIGURATION OF THIS SINGLE FAMILY HOME HAS BEEN ALTERED.
- 2. KITCHEN HAS BEEN REMODELED.
- 3. BATHROOM HAS BEEN REMODELED.
- 4. BATHROOM HAS BEEN ADDED.
- 5. FRONT PORCH HAS BEEN BUILT AND ENCLOSED.
- 6. SECOND ACCESSORY STRUCTURE HAS BEEN BUILT AT BACK OF PARCEL AND CONVERTED TO A SECOND OCCUPIED RESIDENCE.
- 7. UTILITY LAUNDRY CLOSET BUILT AT BACK OF PRIMARY STRUCTURE.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF SPLIT MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF PLUMBING FIXTURES IN KITCHENS AND BATHS.
- 2. INSTALLATION OF WATER SUPPLY AND WASTE LINES TO SERVICE BATHROOM ADDED, BATHROOM REMODEL LAUNDRY AND WATER HEATER.
- 3. INSTALLATION OF WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WIRING CIRCUITS TO SERVICE WATER HEATER, WASHER-DRYER, MECHANICAL SYSTEM, RECEPTACLES AND FIXTURES.
- 2. INSTALLATION OF RECEPTACLES.
- 3. INSTALLATION OF BREAKER PANEL.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF SINGLE FAMILY TO DUPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE16121142
CASE ADDR: 3001 SE 6 AVE
OWNER: ROSSEL GROUP LLC
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 1029.1

POSSIBLE BLOCKAGE OF EMERGENCY ESCAPE AND RESCUE OPENING BY THE ILLEGAL INSTALLATION OF A WATER HEATER IN FRONT OF A WINDOW.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. STRUCTURALLY MODIFYING DOOR OPENING ON EAST

ELEVATION OF STRUCTURE.

Page | 6

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. THE INSTALLATION OF A MINI-SPLIT AIR-CONDITIONING SYSTEM.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF DOOR ON EAST SIDE OF STRUCTURE.
- 2. WINDOWS HAVE BEEN REPLACED.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLATION OF A WOOD FENCE ON THE EAST SIDE OF THE PARCEL.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF GAS WATER HEATER ON THE SOUTH SIDE. WATER HEATER IS SITTING DIRECTLY ON THE GROUND, TPR VALVE IS NOT EXTENDED, THE VENT IS DISPLACED AND UNIT IS IN FRONT OF WINDOW POSSIBLY BLOCKING EMERGENCY ESCAPE OPENING.
- 2. INSTALLATION OF GAS LINES TO SERVICE WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF BREAKER PANEL.
- 2. INSTALLATION OF A HARDWIRED CCTV SYSTEM.
- 3. INSTALLATION OF LIGHTING CIRCUITS.

FBC(2014) 110.2

THE BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE17020603

CASE ADDR: 601 N RIO VISTA BLVD OWNER: SOUTH BANK APTS LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. KITCHEN REMODELING.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVER-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17020835
CASE ADDR: 1000 SW 18 CT
OWNER: SOJA, WIESLAW
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

- 1. WINDOWS AND DOORS REPLACEMENT.
- 2. MODIFICATION OF SOME EXTERIOR OPPENINGS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE18010668
CASE ADDR: 835 NE 16 ST
OWNER: SUNSET TRUST
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2014) 110.2

BEFORE ISSUING A PERMIT, THE BUILDING OFFICIAL IS AUTHORIZED TO EXAMINE OR CAUSE TO BE EXAMINED BUILDINGS, STRUCTURES AND SITES FOR WHICH AN APPLICATION HAS BEEN FILED.

FBC(2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. TWO UNPERMITTED UTILITY SHEDS. INSIDE ONE OF THE SHEDS:
 - A. HOT WATER HEATER.
 - B. WASHER AND DRYER.
 - C. ELECTRICAL AND PLUMBING.
- 2. A LARGE ROOF AND PATIO DECK BUILT WITHOUT A PERMIT.
- 3. VINYL FENCE SEPARATING THE MAIN HOUSE FROM A SEPARATE LIVING QUARTER, WITH A MAKESHIFT ROOF BUILT WITH 2X4'S AND A PLASTIC CORRUGATED ROOF.
- 4. THERE IS AN ELECTRICAL CORD COMING FROM THE ATTIC RUNNING BENEATH THE GROUND TO AN ELECTRICAL MOTORIZED GATE.
- 5. THERE IS A BATHROOM ADDITION AND NO PERMIT HISTORY.
- 6. THE GARAGE AND POSSIBLY ANOTHER AREA SEPARATED AND IS BEING USED AS LIVING QUARTERS. THIS PROPERTY WILL BE CITED FOR WORK WITHOUT A PERMIT AND ILLEGAL OCCUPANCY.
- 7. A/C UNIT INSTALLED (2014) NO PERMIT HISTORY.

FBC (2017) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTIONS BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION.

FBC(2017) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF SINGLE FAMILY WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE18010886
CASE ADDR: 1000 NW 52 ST
OWNER: REISS, STEVEN D
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. TOTAL RENOVATION/DEMOLITION. INCLUDES DRYWALL, PLUMBING, ELECTRICAL BLOCKED UP OPENINGS AND WINDOWS INSTALLED ALL WITHOUT BEING PERMITTED.

CASE NO: CE18011892

CASE ADDR: 12 HARBORAGE ISLE DR
OWNER: MOGHADDAM, ALIREZA AMINI

AMINI, MEHRZAD

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS A SWIMMING POOL AND POOL DECK REMODEL.

2. A BATHROOM REMODEL/ALTERATION.

3. WINDOWS INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2017) 110.1

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE18020982
CASE ADDR: 515 NW 7 TER
OWNER: BARR, ESSIE MAE

SMITH, EDWARD H EST E

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WINDOWS AND DOORS INSTALLED WITHOUT A PERMIT.

FBC(2017) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTIONS BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES.

CASE NO: CE18021657
CASE ADDR: 3320 NW 65 ST
OWNER: CHAPMAN, TRAVIS

VANCE, KENNETH

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PAVERS INSTALLED IN THE FRONT YARD.

2. PVC FENCE.

3. EXTERIOR DOOR AND WINDOW.

4. SECURITY CAMERA.

FBC(2017) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTIONS BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED.

FBC(2017) 110.2

BEFORE ISSUING A PERMIT, THE BUILDING OFFICIAL IS AUTHORIZED TO EXAMINE OR CAUSE TO BE EXAMINED BUILDINGS, STRUCTURES AND SITES FOR WHICH AN APPLICATION HAS BEEN FILED.

CASE NO: CE18022091 CASE ADDR: 705 SE 10 ST

OWNER: GRABEL, JOSHUA F & LACEY

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOOD FENCE

2. INSTALLED A PLANTER, PATIO AND RETAINING WALL WITHIN THE SWALE ON THE ROW UP TO THE EDGE OF

PAVEMENT.

CASE NO: CE18050382 CASE ADDR: 1410 SW 3 AVE

OWNER: CARNEY, MARIA ANN &

CARNEY, PATRICK JR & BERBET T M

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CHANGE IN OCCUPANCY AND USE.

2. WINDOW.

3. INDUSTRIAL EQUIPMENT AND MACHINES.

4. PLUMBING WORKS.5. ELECTRICAL.6. MECHANICAL.

CASE NO: CE18051613

CASE ADDR: 1101 NW 54 ST

OWNER: 1163 HOLDINGS LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. INSTALLING PARKING GARAGE FLOOR COVER.

CASE NO: CE18062646
CASE ADDR: 1236 NE 18 AV
OWNER: WARREN, KEVIN
WARREN, LINDA

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. NEW ELECTRICAL METER AND WEATHER HEAD.

ELECTRICAL OUTLET.
 INTERIOR RENOVATION.

4. BRICK PAVERS.

5. OUTDOOR GROUND LIGHTING.

6. OUTDOOR OUTLETS.7. SECURITY CAMERAS.8. FLOOD LIGHTS.

9. 4X4 POST.

CASE NO: CE18091868
CASE ADDR: 2665 SW 6 CT
OWNER: JULES, BETTIE
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. ROOM ADDITION IN THE BACK OF THE HOUSE.

CASE NO: CE18100735 CASE ADDR: 901 N BIRCH RD

OWNER: MARINE COLONY VILLAS CO-OP

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:
1. INSTALLING A CBS TRASH ENCLOSURE WITHOUT A

PERMIT.

CASE NO: CE18101715
CASE ADDR: 1005 NE 16 PL
OWNER: DROUBI, ELIAS
ZHGULEVA, JULIA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. RENOVATIONS OF THE KITCHEN AND BATHROOM.

2. THE MECHANICAL, ELECTRICAL AND PLUMBING HAVE ALSO BEEN ALTERED WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS.

CASE NO: CE18101875
CASE ADDR: 532 SW 10 AV
OWNER: ROMERO, MICHAEL
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:
1. EXTENDED CONCRETE DECK OVER THE SEAWALL.

2. REAR WOOD FENCE.

3. NEW AC UNIT.

4. NEW KITCHEN SINK, TWO BATHROOMS REMODELED WITH

NEW SINKS AND COMMODE.

5. EXHAUST VENT OVER THE STOVE.

CASE NO: CE18110066

CASE ADDR: 784 W EVANSTON CIR

OWNER: AUGUSTE, TONY INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. ENCLOSURE OF THE GARAGE DOOR OPENING.

2. REPLACED 3' DOOR ON WEST SIDE OF THE GARAGE.
3. REPLACED WINDOW ON THE WEST SIDE OF THE GARAGE.

CASE NO: CE18111242 CASE ADDR: 1426 NE 60 ST OWNER: PALAU INC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

INCLUDING BUT NOT LIMITED TO:

1. NEW BOAT DOCK INSTALLED OVER EXISTING DOCK.
2. TIKI HUT INSTALLED WITHOUT ZONING PERMIT.

3. NEW A/C CONDENSER UNIT INSTALLED.

4. WOOD TRELLIS INSTALLED ABOVE FRONT ENTRANCE.

CASE NO: CE18120956

CASE ADDR: 701 NW 19 ST # 112

OWNER: HERMAN, KATIA ALVES DE CAMPOS

HERMAN, MICHAEL

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. DEMOLITION OF MASTER BATHROOM.

2. RELACEMENT OF ELECTRICAL OUTLETS THROUGHOUT AND REWIRED INSIDE WALLS.

3. ENLARGEMENT OF OPENING INTO THE KITCHEN AND ALCOVE OF LIVING ROOM.

4. REPLACEMENT OF WATER HEATER.

CASE NO: CE18121809
CASE ADDR: 615 SW 4 AVE

OWNER: FARREN, WARD EVEN JR

CARRIGAN, BAILEY

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

FULL KITCHEN REMODEL.
 TWO BATHROOMS REMODELED.

3. MECHANICAL, ELECTRICAL AND PLUMBING

ALTERATIONS.

PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

CASE NO: CE19020171
CASE ADDR: 1731 NE 3 AVE
OWNER: CAMPOS, ROLANDO
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN EXTENSIVELY ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

- 1. THE KITCHENS AND BATHROOMS HAVE BEEN COMPLETELY RENOVATED INCLUDING ALTERATIONS OF INTERIOR WALLS AND REMOVING AND REPLACING DRYWALL AND TILE BACKING BOARDS.
- 2. THE PLUMBING FOR THIS PROPERTY HAS BEEN ALTERED.
- 3. THE ELECTRICAL FOR THIS PROPERTY HAS BEEN ALTERED.
- 4. THE MECHANICAL SYSTEM FOR THIS PROPERTY HAS BEEN ALTERED.
 ALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2017) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2017) 110.1

THIS PROPERTY WILL REQUIRE A FOLLOW UP SITE VISIT AND COMPLETE INSPECTION OF THE PROPERTY TO DETERMINE EXACTLY WHAT WORK HAS OR HAS NOT BEEN PERFROMED. PLEASE CONTACT ME TO SCHEDULE AN INSPECTION AS SOON AS POSSIBLE. ROBERT MASULA 954-828-5292.

CASE NO: CE19021611

CASE ADDR: 4812 NE 23 AVE # 8
OWNER: COLLIS, GRAHAM
MALDONADO, BIANCA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

- 1. KITCHEN HAS BEEN REMODELED INCLUDING REMOVING AN INTERIOR PARTITION, REMOVING AND REPLACING ELECTRICAL AND PLUMBING FIXTURES.
- 2. THE INTERIOR ELECTRICAL PANEL HAS BEEN REMOVED AND REPLACED.
- 3. THE A/C MECHANICAL UNIT HAS BEEN REMOVED AND REPLACED.

ALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2017) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

CASE NO: CE19030061

CASE ADDR: 1030 IROQUOIS AVE
OWNER: HUGHLEY, STANLEY A
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ADDITION BUILT AND COMPLETED WITH AN EXPIRED PERMIT.

CASE NO: CE19030306
CASE ADDR: 808 NE 14 ST
OWNER: AMD HOLDINGS LLC
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS MADE WHICH HAVE ILLEGALLY

SUB-DIVIDED THE PROPERTY WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

FBC(2017) 116.1.1

THIS PROPERTY HAS BEEN SUBJECT TO A FIRE WHICH WILL REQUIRE PERMITS TO MAKE NEEDED REPAIRS AND

MAKE THE PROPERTY SAFE.

FBC(2017) 110.2

THIS PROPERTY WILL REQUIRE A FOLLOW UP SITE VISIT

AND COMPLETE INSPECTION OF THE PROPERTY TO

DETERMINE EXACTLY WHAT WORK HAS OR HAS NOT BEEN PERFORMED. PLEASE CONTACT ME TO SCHEDULE AN INSPECTION AS SOON AS POSSIBLE. ROBERT MASULA

954-828-5292.

CASE NO: CE19031213 CASE ADDR: 2144 NE 62 CT

OWNER: MARO SOUTHFLORIDA LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

1. THE KITCHEN AND TWO BATHROOMS HAVE BEEN

COMPLETELY DEMOLISHED.

2. THERE IS NEW ELECTRICAL WORK INSTALLED

THROUGHOUT THE HOUSE.

3. THERE IS NEW PLUMBING WORK INSTALLED IN THE

KITCHEN AND TWO BATHROOMS.

4 THE MECHANICAL SYSTEM HAS BEEN REPLACED.

THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

.....

CASE NO: CE19031344 CASE ADDR: 820 NE 17 AVE

OWNER: V P NE 17TH AVE LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING AND FRANMING.
- 2. NEW PAVERS INSTALLED.
- 3. NEW PLUMBING INSTALLATION IN KITCHEN AND BATHROOMS.
- 4. NEW EXTERIOR ELECTRICAL INSTALLATION.
- 5. NEW ELETRICAL PANEL AND OUTLETS.
- 6. A/C INSTALLED.
- 7. NEW DOORS AND FRAMES.
- 8. NEW WINDOWS.
- 9. DOORS AND WINDOWS ENCLOSURE.

FBC(2017) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY

REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND

ISSUANCE OF ALL AND ANY PERMITS AND/OR

DETERMINATION OF COMPLIANCE WITH THE FLORIDA

BUILDING CODE.

CASE NO: CE19031345 CASE ADDR: 828 NE 17 AVE

OWNER: V P NE 17TH AVE LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2017) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING AND FRAMING.
- 2. NEW PULMBING INSTALLATION (FIXTURES AND PIPE).
- 3. NEW ELECTRICAL INSTALLATION.
- 4. NEW PAVERS INSTALLED.
- 5. NEW DOORS AND WINDOWS.

FBC(2017) 110.2

(RIGHT TO INSPECT)

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY

REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND

ISSUANCE OF ALL AND ANY PERMITS AND/OR

DETERMINATION OF COMPLIANCE WITH THE FLORIDA

BUILDING CODE.

CASE NO: CE19031519 CASE ADDR: 4820 NE 26 AV

OWNER: 26TH LLC INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

1. THE PROPERTY HAS BEEN COMPLETELY REMODELED WITH INTERIOR ALTERATIONS, KITCHEN AND BATHROOM REMODEL, FRAMING AND DRYWALL, ELECTRICAL,

MECHANICAL AND PLUMBING WORK PERFORMED WITHOUT THE

REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2017) 110.2

THIS PROPERTY WILL REQUIRE A FOLLOW UP SITE VISIT

AND COMPLETE INSPECTION OF THE PROPERTY TO

DETERMINE EXACTLY WHAT WORK HAS OR HAS NOT BEEN PERFORMED. PLEASE CONTACT ME TO SCHEDULE AN INSPECTION AS SOON AS POSSIBLE. ROBERT MASULA

954-828-5292.

CASE NO: CE19031752 CASE ADDR: 1716 NE 7 ST

OWNER: THOMAS H FRED JR REV LIV TR

FRED, THOMAS H JR TRSTEE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS A FENCE INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

2. THE WINDOWS AND DOORS AT THIS PROPERTY HAVE BEEN REMOVED AND REPLACED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE19032238
CASE ADDR: 215 SW 21 TER
OWNER: TREPPUR LLC
INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: INTERIOR OFFICE BUILT: FRAMING, DRYWALL, ELECTRICAL WIRING. SECOND STORY WALL FRAMING

WITHOUT INTERIOR DRYWALL.

CASE NO: CE19040104
CASE ADDR: 1611 NE 56 ST
OWNER: BECHO, ANGELA
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

INCLUDING BUT NOT LIMITED TO:

1. INSTALLED ASPHALT PAVEMENT AT THE FRONT OF THE

STRUCTURE.

CASE NO: CE19040127
CASE ADDR: 1702 NE 9 ST

OWNER: V P NE 17TH AVE LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2017) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:
1. SOFFIT VENTS.

PAVERS.
 FENCE.
 PLUMBING.

5. WINDOWS AND DOORS, WALL ENCLOSURES.

6. MECHANICAL A/C.

7. ELECTRICAL INSTALLATION.

CASE NO: CE19040417 CASE ADDR: 2251 NE 62 ST

OWNER: CSI-MPI CORPORATION

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 110.2

THIS PROPERTY WILL REQUIRE A FOLLOW UP SITE VISIT

AND COMPLETE INSPECTION OF THE PROPERTY TO
DETERMINE EXACTLY WHAT WORK HAS OR HAS NOT BEEN
PERFORMED. PLEASE CONTACT ME TO SCHEDULE AN
INSPECTION AS SOON AS POSSIBLE. ROBERT MASULA

954-828-5292.

FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

- 1. THE KITCHEN AND BATHROOMS HAVE BEEN REMODELED INCLUDING REMOVING AND REPLACING PLUMBING FIXTURES.
- 2. A TRELLIS HAS BEEN BUILT THAT IS ATTACHED TO THE REAR OF THE HOUSE.
- 3. A GAZEBO HAS BEEN BUILT IN THE REAR CORNER OF THE YARD.

THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE19040882
CASE ADDR: 1400 NE 16 CT
OWNER: MDR MOTORS LLC

% MICHAEL GRIECO JR

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS A LARGE OFFICE TRAILER PLACED ON THIS PROPERTY WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

CASE NO: CE19041885 CASE ADDR: 225 SW 32 ST

OWNER: CAROLE J LITTLEFIELD TR

LITTLEFIELD, CAROLE J TRSTEE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:
1. ERECTING A LARGE AWNING/CANOPY STRUCTURE

WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE19051470
CASE ADDR: 201 SW 7 AVE
OWNER: SKY201 LLC
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

- 1. THE ROOF COVERING FOR THE SECOND FLOOR UNIT HAS BEEN REMOVED AND REPLACED.
- 2. THE WINDOWS AND DOORS ON THE SECOND FLOOR HAVE BEEN REMOVED AND REPLACED.
- 3. THE A/C MECHANICAL UNIT ON THE SECOND FLOOR HAS BEEN REMOVED AND REPLACED.
- 4. MISCELLANEOUS ELECTRICAL WORK AND LOW VOLTAGE WORK ON THE SECOND FLOOR HAS BEEN PERFORMED.
- 5. THE SECOND FLOOR USAGE WAS FOR RESIDENTIAL. THE COMPANY DELIVERY DUDES IS OCCUPYING THE SECOND FLOOR. A CHANGE OF OCCUPANCY WILL NEED TO BE APPLIED FOR AND OBTAIN A CERTIFICATE OF THESE ALTERATIONS HAVE BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE19060822 CASE ADDR: 300 SW 12 ST

OWNER: REILLY RYAN INVESTMENT GROUP LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

- IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:
- 1. EXTENSIVE INTERIOR AND EXTERIOR DEMOLITION WITHOUT THE REQUIRED PERMITS.
- 2. NEW FORMWORK, STEEL RE-BAR AND CONCRETE BLOCK INSTALLED.

THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE CODE OF ORDINANCES

CASE NO: CE19041187

CASE ADDR: 1207 CORDOVA RD OWNER: VELOCITY 3 LLC INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

- 1. NEW FENCE INSTALLED ON THE PROPERTY.
- 2. THE A/C SYSTEM WAS REPLACED. THE DUCT WORK THROUGHOUT THE HOUSE HAS BEEN REPLACED AND IS NOT A CONVENTIONAL A/C DUCT SYSTEM.
- 3. THERE HAS BEEN ELECTRICAL ALTERATIONS MADE TO THIS PROPERTY:
- A. THE EXTERIOR ELECTRICAL PANEL WAS REPLACED.
- B. THERE ARE BETWEEN 38 TO 40 HI-HAT LIGHT FIXTURES IN THIS HOUSE. THERE IS NO PERMIT RECORD FOR THESE HI-HAT LIGHT FIXTURES.
- 4. THE KITCHEN AND TWO BATHROOMS HAVE BEEN COMPLETELY REMODELED INCLUDING REMOVING AND REPLACING ALL THE PLUMBING FIXTURES.
 THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2017) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

CASE NO: CE17101770
CASE ADDR: 550 N BIRCH RD

OWNER: NORTH BEACH HOTEL LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. INTERIOR RENOVATION TO INCLUDE: DRYWALL

PLUMBING, AND ELECTRICAL WORK.

FBC(2014) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTIONS BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED.

FBC(2014) 110.2

BEFORE ISSUING A PERMIT, THE BUILDING OFFICIAL IS AUTHORIZED TO EXAMINE OR CAUSE TO BE EXAMINED BUILDINGS, STRUCTURES AND SITES FOR WHICH AN APPLICATION HAS BEEN FILED.

._____

CASE NO: CE16111504 CASE ADDR: 2865 NE 35 CT

OWNER: CASH, THOMAS V & HILLARY A

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. SHADE STRUCTURE BUILT IN THE BACKYARD.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE18110565

CASE ADDR: 460 CAROLINA AVE OWNER: 0'NEILL, PAOLA INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: 9-1.(D)

THERE IS A MAJOR INTERIOR RENOVATION GOING ON WITHOUT THE REQUIRED PERMITS AS PER THE FLORIDA BUILDING CODE BORA EDITION SECTION 105.1, WHICH INCLUDES STRUCTURAL, ELECTRICAL AND PLUMBING WORK.

CASE NO: CE17071043

CASE ADDR: 6250 N ANDREWS AVE # 25

OWNER: DOUBLE MOUNTAIN DEV VENTURES LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. INTERIOR ALTERATIONS TO FLOOR PLAN.

2. INTALLED ELECTRICAL.3. INSTALLED BATHTUBS

4. INSTALLED WATER HEATERS.

FBC(2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE17101744

CASE ADDR: 3000 TERRAMAR ST

OWNER: NORTH BEACH HOTEL LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DEMOLITION OF POOL BATHHOUSE.

2. BREACH OF FIRE WALLS IN POOL BATHHOUSE.

3. WINDOWS AND DOORS INSTALLED.

FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND DEMOLITION WORK HAS BEEN PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. POOL BATHHOUSE INTERIOR DEMOLITION.
- 2. BREACH FIRE PARTITION BY REMOVAL OF DRYWALL IN POOL BATHHOUSE.

FBC(2014) 110.2

BEFORE ISSUING A PERMIT, THE BUILDING OFFICIAL IS AUTHORIZED TO EXAMINE OR CAUSE TO BE EXAMINED BUILDINGS, STRUCTURES AND SITES FOR WHICH AN APPLICATION HAS BN FILED.

CASE NO: CE18061643 CASE ADDR: 931 NW 53 CT

OWNER: LORD PROPERTIES II LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR ALTERATIONS/BUILDING INTERIOR OFFICE INSIDE A WAREHOUSE.

- 2. INSTALLING SECURITY/SURVEILLANCE CAMERA.
- 3. ELECTRICAL UPGRADE WORK.

CASE NO: CE18102205 CASE ADDR: 430 FLORIDA AVE

OWNER: DREAM HOMES LEASING LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REPLACED DOORS AND WINDOWS.
- 2. NEW COLUMN FRONT PORCH BEAM SUPPORT.
- 3. NEW FRONT PORCH LIGHTING.
- 4. NEW FLOOD LIGHTS EXTERIOR CORNERS.
- 5. REMODELED BATHROOMS AND KITCHEN.
- 6. A/C UNIT INSTALLED.
- 7. ELECTRICAL PANEL CHANGE OUT.
- 8. NEW HOT WATER HEATER.

CASE NO: CE19010207 CASE ADDR: 729 SW 4 CT

OWNER: AWH&T INVESTMENT LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ERECTION OF A WOOD FENCE.

CASE NO: CE19012272

CASE ADDR: 1071 TENNESSEE AVE

OWNER: WHITSETT, WILLIAM ROBERT

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:
1. CARPORT PARTIALLY ENCLOSED WITH CBS BLOCK,

CONCRETE AND WOOD FRAMING.